



CIP CID #1952

Instructions

Hot Liquor Tank Cleaning

STEP

1

- Blend a solution of 4 to 5 oz. per 1 gallon of water.

STEP

2

- Circulate for 15-20 minutes at a temperature of 80°- 145°F.

STEP

3

- Hose Rinse.

STEP

4

- Sanitize to Local Codes.

Recommendations for Optimal Performance

- Utilization of acidified rinse is key after each caustic cycle to minimize caustic film which may cause foaming
- Utilization of acidified rinse is key after each caustic cycle to minimize the buildup of beer stone

Sales@stone-leigh.com
Stone-Leighbrewcleaners.com
@stoneleighbrewcleaner
508-465-0230