



Caustic #1645 / #1620 / #1300
CIP CID #1832 / CIP CID #1840

Instructions

Caustic-Acid Rinse-Sanitize

STEP

1

Hose Rinse

- Thoroughly rinse kettle with warm water at 110°-130°F to remove the bulk of the soil load.

STEP

2

Caustic Wash

- Apply a strong alkaline #1645 or #1620 @ 2 ounce of PBC #1300 per gallon of water (130°-160°F).
- Clean and circulate for 15-25 minutes.
- Drain and Hose Rinse.

STEP

3

Acid Rinse

- Create of blend of Cip Cid #1832 or Cip Cid #1840 @ 2 or 3 ounces per 5 gallons.
- Circulate the solution for 15-20 minutes at a temperature of 100°-140°F.

STEP

4

- Sanitize to Local Codes.

Sales@stone-leigh.com
Stone-Leighbrewcleaners.com
@stoneleighbrewcleaner
508-465-0230